



Abiomed, Inc.
22 Cherry Hill Dr.
Danvers, MA 01923 USA
Phone: +1 978-646-1400
Fax: +1 978-777-8411
www.abiomed.com

FSN Ref: 2026-FSN-0000140

FSCA Ref: 2026-FA-0000140

Date: 2026-06-01

URGENT Field Safety Notice
AIC EPC Software Error

For Attention of*: All Automated Impella Controller (AIC)

Contact details of local representative (name, e-mail, telephone, address etc.)*

E-Mail: DL-EUFSCA@its.jnj.com
Malte Flory +49 172 4556857
Abiomed Europe GmbH
Neuenhofer Weg 3
D-52074 Aachen
Customer Service Tel.: +800 0 22 466 33

FSN Ref: 2026-FSN-0000140

FSCA Ref: 2026-FA-0000140

URGENT Field Safety Notice (FSN)
AIC EPC Software Error

1. Information on Affected Devices*	
1.	1. Device Type(s)* All Automated Impella Controller (AIC)
1.	2. Commercial name(s)* Automated Impella Controller (AIC)
1.	3. Primary clinical purpose of device(s)* The Automated Impella Controller provides three functions to the operation of the Impella Catheter: <ul style="list-style-type: none"> • The controller provides an interface for monitoring and controlling the function of the Impella Catheter. • The controller provides a purge fluid to the Impella Catheter. • The controller provides backup power when the Impella Ventricular Support Systems are operated away from AC power.
1.	4. Device Model/Catalogue/part number(s)* 0042-0000-EU; 0042-0000-UK; 0042-0010-EU; 0042-0010-UK; 0042-0040-EU; 0042-0040-UK (not all models apply to all countries)
1.	5. Software version All AIC Software version 6.0.1, 6.0.2, 6.0.3, and 7.1 onwards
1.	6. Affected serial or lot number range Not relevant – all AIC are impacted
1.	7. Associated devices All Impella heart pump models are run by the Automated Impella Controller (AIC). The user monitors the pump through the AIC user interface. The AIC also drives the Purge Cassette to provide purge fluid to the Impella pumps.

2. Reason for Field Safety Corrective Action (FSCA)*	
2.	1. Description of the product problem* Abiomed initiates a correction by informing users of a potential software error in the Automated Impella Controller (AIC) when used in conjunction with left ventricular Impella devices and to provide recommendations on what to do if the issue occurs. Product is not being removed, and hospital inventory may continue to be used. Abiomed has identified that when a patient is treated with a left ventricular Impella device and experiences an extended period (>80 minutes) with no residual pulsatility (<12 mmHg on the aortic placement signal), the Automated Impella Controller (AIC) may be forced to restart because of an internal software error. This can occur if there is a sudden change in left ventricular pressure (LVP) while the left ventricular pressure calculation is active (level of support above P-3). Disabling the aortic placement signal and the LVP display does not prevent the AIC from restarting.

FSN Ref: 2026-FSN-0000140

FSCA Ref: 2026-FA-0000140

	<p>During the restart, the AIC screen will turn black without further alert, and the pump will stop, during which the patient is unsupported by the Impella system and regurgitation via the cannula may occur. After the AIC restarts, the pump will automatically ramp up speed to the previous P-level. The total time from pump stop to reach the previous P-level may take up to 75 seconds based on preliminary data.</p> <p>Replacement of the AIC with another AIC would not resolve the potential for an AIC restart.</p> <p>Recommendations for the customers:</p> <ul style="list-style-type: none"> • All Abiomed customers who have an Automated Impella Controller SW version 6.0.1, 6.0.2, 6.0.3, and 7.1 onwards will receive the notification. • Product is NOT being removed, and hospital inventory can continue to be used. • In the scenario of extended (>80 min) lack of pulsatility (< 12 mmHg), followed by a sudden change in LVP an AIC console restart will occur during support levels greater than P-3. Additional hemodynamic support may be required in this hemodynamically compromised population. • If such an episode is encountered, a console exchange is unnecessary as the phenomenon will recur on the exchange device. • In patients additionally supported with Veno-arterial ECMO, unloading of the ventricle at a level of support of P-3 or lower will avoid the restart from happening as the LVP calculator causing the issue is off. • Abiomed is actively working on a software update to the AIC to address this issue. <p>At Abiomed, our priority is to our customers and their patients, and that includes the safe and effective use of our products. If you have questions or concerns regarding this notice, please contact DL-EUFSCA@its.jnj.com or your local clinical field staff.</p>
2.	<p>2. Hazard giving rise to the FSCA*</p> <p>The software anomaly issue leads to a sudden and unexpected pump stop for the duration of 35 to 50 seconds. Exposure to the reboot of the AIC may result or can be reasonably expected to result in inadequate hemodynamic support which is usually tolerated by patients with sufficient native cardiac output or concomitant alternative mechanical support.</p>
2.	<p>3. Probability of problem arising</p> <p>There is a low probability of the problem arising. From January 1, 2024, to February 28, 2026, a review identified the software issue occurred in 0.006% of cases (8 reported complaints out of 125,714 cases performed).</p>
2.	<p>4. Predicted risk to patient/users</p> <p>During standard clinical use scenarios, it is accepted that the user may replace the AIC controller. Usually, this will result in a tolerated temporary loss of support. There is an</p>

FSN Ref: 2026-FSN-0000140

FSCA Ref: 2026-FA-0000140

	<p>anticipated associated risk of a loss of hemodynamic support during the transition, which is done out of clinical necessity. Physicians are expected to take reasonable measures and use clinical acumen to determine if transfer between devices is necessitated by the patient. This is achieved through careful preparation, planning, and occurs in a controlled environment.</p> <p>The current issue on the other hand leads to a sudden and unexpected pump stop. Exposure to the reboot of the AIC may result or can be reasonable expected to result in a user inconvenience (S1) and inadequate hemodynamic support (S3) which is usually tolerated by patients with sufficient native cardiac output or concomitant alternative mechanical support. As the issue's scenario is explicitly triggered by prolonged low pulsatility, the issue is predominantly linked to two distinct patient cohorts of which the cohort with low native pulsatility due to a low ejection fraction is specifically vulnerable whereas the other is protected by a concomitant hemodynamic support by an ECMO. Device replacement (S3) which is also considered to be a reversible injury can also be triggered. Only under unusual circumstances, exposure may result in loss of hemodynamic support (S5) which is considered a life-threatening injury with the potential for permanent impairment. To date, 8 confirmed complaints have been reported. Two of these had an outcome reported as death, one without and one with immediate hemodynamic consequences. The product issue increases the risk to the patient, but the life-sustaining benefit of Impella support is maintained regardless of action or inaction.</p>
2.	<p>5. Further information to help characterise the problem</p> <p>Please follow instructions in section 2.1</p>
2.	<p>6. Background on Issue</p> <p>A review of global complaints from January 1, 2024, to February 28, 2026, identified the software issue in 0.006% of cases (8 reported complaints out of 125,714 cases performed). The complaints review determined that there has been two (2) patient deaths where the association of the above-described restart to the patient outcome could not be excluded. There have been two (2) cases where the failure resulted in a pump stop. In these two cases, the user chose to exchange the AIC console, which is considered a medical intervention and reportable as a serious injury. As a reminder, replacement of the AIC with another AIC would not resolve the potential for an AIC restart.</p>
2.	<p>7. Other information relevant to FSCA</p> <p>N/A</p>

3. Type of Action to mitigate the risk*	
3.	<p>1. Action To Be Taken by the User*</p> <p> <input checked="" type="checkbox"/> Identify Device <input type="checkbox"/> Quarantine Device <input type="checkbox"/> Return Device <input type="checkbox"/> Destroy Device </p> <p> <input type="checkbox"/> On-site device modification / inspection </p> <p> <input type="checkbox"/> Follow patient management recommendations. </p> <p> <input checked="" type="checkbox"/> Take note of amendment / reinforcement of Instructions For Use (IFU) </p> <p> <input checked="" type="checkbox"/> Other <input type="checkbox"/> None </p> <p>Follow recommendations described in section 2.1</p>

FSN Ref: 2026-FSN-0000140

FSCA Ref: 2026-FA-0000140

4.	3. For Updated FSN, key new information as follows:	
	N/A	
4.	4. Further advice or information already expected in follow-up FSN? *	No
4.	5. If follow-up FSN expected, what is the further advice expected to relate to:	
	N/A	
4.	6. Anticipated timescale for follow-up FSN	N/A
4.	7. Manufacturer information (For contact details of local representative refer to page 1 of this FSN)	
	a. Company Name	Abiomed Inc.
	b. Address	22 Cherry Hill Drive, Danvers, MA, US
	c. Website address	www.heartrecovery.com
4.	8. The Competent (Regulatory) Authority of your country has been informed about this communication to customers.	
4.	9. List of attachments/appendices:	None
4.	10. Name/Signature	Malte Flory Senior Manager, Commercial Quality EMEA

	Transmission of this Field Safety Notice
	<p>This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where Impella pumps have been transferred. Please transfer this notice to other organisations on which this action has an impact. (As appropriate) Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action and keep this FSN together with the existing version of the product IFU.</p> <p>Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback. *</p>

FSN Ref: 2026-FSN-0000140 FSCA Ref: 2026-FA-0000140

URGENT Field Safety Notice (FSN)
AIC EPC Software Error
Customer Reply Form

1. Field Safety Notice (FSN) information	
FSN Reference number*	2026-FA-0000140
FSN Date*	2026-06-01
Product/ Device name*	Automated Impella Controller (AIC)
Product Code(s)	0042-0000-EU, 0042-0010-EU, 0042-0040-EU, 0042-0000-UK, 0042-0010-UK; 0042-0040-UK.

2. Customer Details	
Account Number	
Healthcare Organisation Name*	
Organisation Address*	
Department/Unit	
Shipping address if different to above	
Contact Name*	
Title or Function	
Telephone number*	
Email*	

If additional organizations are covered by your response, please ensure their details are recorded in the table on the next page.

3. Customer action undertaken on behalf of Healthcare Organisation		
<input type="checkbox"/>	I confirm receipt of the Field Safety Notice and that I read and understood its content*	Complete or enter N/A
<input type="checkbox"/>	I performed all actions requested by the FSN*	Complete or enter N/A
<input type="checkbox"/>	The information and required actions have been brought to the attention of all relevant users*	Complete or enter N/A
<input type="checkbox"/>	I have a query please contact me	Enter contact details if different from above and brief description of query
Print Name*		
Signature*		
Date*		

4. Return acknowledgement to sender	
Email	DL-EUFSCA@its.inj.com
Customer Helpline	+800 0 22 466 33
Postal Address	Abiomed GmbH Att. of Malte Flory Neuenhofer Weg 3 52074 Aachen -Germany
Web Portal	www.abiomed.eu ; www.heartrecovery.eu
Deadline for returning the customer reply form*	Please return within 7 working days

Mandatory fields are marked with *

FSN Ref: 2026-FSN-0000140

FSCA Ref: 2026-FA-0000140

This Customer reply form also applies to these additional organizations:

--

It is important that your organisation takes the actions detailed in the FSN and confirms that you have received the FSN.

Your organisation's reply is the evidence we need to monitor the progress of the corrective actions.