

Product

Lot **Expiry**

Date of Notification

Details of problems with this device:

2 Cell Antibody screen lot 3557 has been identified as producing false positive reactions for some customers. An additional batch with Lot 3558 has been manufactured. This batch was replaced in CellMedia only with an advisory notice but following a further customer contact regarding the CellStab product the decision has been made to replace CellStab and Aelsevers variants.

Action to be taken by user:

If you have been experiencing a problem with batch 3557 please discard it and the associated product profile and replace with the enclosed batch labelled 3558 and its associated profile.

Please complete the form below to acknowledge receipt of this advisory notice.

This notice needs to be passed on to all those who need to be aware within your organisation and to any organisation where this device has been transferred (if appropriate). Please maintain awareness on this notice and resulting action to an appropriate period to ensure effectiveness of this notice.

Issued for NHSBT Reagents by **Title**

Contact details

User contact – Please return this slip to the address or email above

I confirm that I have received the advisory notice regarding the device below and have taken the required action

Hospital **Pulse Code**

Name	Signature	Date
Product Name	Lot Number	Expiry